



Summer Camp 2024

Forensic Engineering Practice Lessons

Case Study of a Multi Building Cladding Failure
in New Zealand

Brian Hubbs, P.Eng.
Principal, RDH Building Science Inc.
bch@rdh.com







Forensic Engineering
is

“CSI For Buildings”

 **FORENSIC**

CRIME SCENE

CRIME SCENE

CRIME SCENE

SCIENTIST

JUST LIKE A

NORMAL SCIENTIST

BUT WAY COOLER

Forensic Engineering is NOT

- Cherry Picking
- Code quoting
- Red Herrings
- Guessing
- Surveying

Four engineers get into a car. The car won't start.

**The Mechanical engineer says:
"It's a broken starter".**

**The Electrical engineer says:
"Dead battery".**

**The Chemical engineer says:
"Impurities in the gasoline".**

**The IT engineer says:
"Hey guys, I have an idea how about we all get out of the car and get back in".**

Typical Plaintiffs' Case

1. Water got in - made things bad!
2. Cladding separates the rot from rain.
3. Did some testing.... it failed.
4. Problem = defective product/installation
5. Same system on all buildings.
6. System will eventually fail everywhere.
7. Everything needs to be replaced.

QED ?

(Quod Erat Demonstrandum)

“scientific microphone drop”



Typical Defendants' Case:

1. Cladding was not installed perfectly
2. Maintenance was not perfect
3. Some areas performing well
4. Did some testing - Passed
5. Cladding is good
6. Problem: Bad Installation & maintenance

QED ?



Background

- 833 schools in New Zealand,
- Water infiltration and decay,
- NZ experts investigating failure,
- NZ Building Code:
 - Install wall assembly in accordance with manufacturer's instructions.
 - NZ 4284 water test.
- **\$1.4 Billion**

New Zealand schools leak millions

Daniel Adams · 05:00, Mar 04 2013




BRUCE MERCER/FAIRFAX NZ

FINALLY DRY: Te Rapa School principal Vaughan Franklin is happy his school's leaky issues have finally been resolved.

Thirty more schools have been confirmed as having leaking buildings that are expected to cost up to \$1.4 billion to repair.

Official information released to the Waikato Times also shows legal action over issues caused by poor design, materials failure,

Center of Wall Issues



Interface Details
Included in Manufacturers Installation Instructions



Roofing and A-Typical Interface Details Not Included in Manufacturers Installation Instructions



RDH's Forensic Mandate

- 1 Would cladding system have failed if built in accordance with manufacturer's instructions
- 2 Why do failures occur in some areas and not others



NZ is Different !



New Zealand Exposure Risk Score Categories


Risk Factor	Score(5)	Risk severity	Comments
A: Wind zone	0	Low risk	Low <i>wind zone</i> as described by NZS 3604
	0	Medium risk	Medium <i>wind zone</i> as described by NZS 3604
	1	High risk	High <i>wind zone</i> as described by NZS 3604
	2	Very high risk	Very High <i>wind zone</i> as described by NZS 3604
	2	Extra high risk	Extra High <i>wind zone</i> as described in NZS 3604 (4)
B: Number of storeys	0	Low risk	One <i>storey</i>
	1	Medium risk	Two <i>storeys</i> in part
	2	High risk	Two <i>storeys</i>
	4	Very high risk	More than two <i>storeys</i>
C: Roof/wall junctions	0	Low risk	Roof-to-wall intersection fully protected (e.g. hip and gable roof with <i>eaves</i>)
	1	Medium risk	Roof-to-wall intersection partly exposed (e.g. hip and gable roof with no <i>eaves</i>)
	3	High risk	Roof-to-wall intersection fully exposed (e.g. <i>parapets</i> , <i>enclosed balustrades</i> or <i>eaves</i> at greater than 90° to vertical with soffit <i>lining</i>)
	5	Very high risk	Roof elements finishing within the boundaries formed by the exterior walls (e.g. lower ends of aprons, <i>chimneys</i> , <i>dormers</i> etc)
D: Eaves width ⁽¹⁾⁽²⁾	0	Low risk	Greater than 600 mm for single storey
	1	Medium risk	451–600 mm for single storey, or over 600 mm for two storey
	2	High risk	101–450 mm for single storey, or 451–600 mm for two storey, or greater than 600 mm above two storey
	5	Very high risk	0–100 mm for single storey, or 0–450 mm for two storey, or less than 600 mm above two storey
E: Envelope complexity	0	Low risk	Simple rectangular, L, T or boomerang shape, with single <i>cladding</i> type
	1	Medium risk	Moderately complex, angular or curved shapes (e.g. Y or arrowhead) with no more than two <i>cladding</i> types
	3	High risk	Complex, angular or curved shapes (e.g. Y or arrowhead) with multiple <i>cladding</i> types
	6	Very high risk	As for High risk, but with junctions not covered in C or F of this table (e.g. box windows, pergolas, multi-storey re-entrant shapes etc)

MAX Risk = 22

Additional NZ Exposure Risks: Driving Rain


→ Wind zones do not take into account prevailing wind direction for **Driving Rain**


→ Wind within 90° of the facing direction contributes to driving rain



Additional NZ Exposure Risks: Solar Radiation

→ North-facing elevations shown to be at lower risk of moisture accumulation due to solar drying potential





The Problematic Wall Assembly

Interior

Interior Finish


Wall Framing

Batt Insulation in Cavity





Building Paper

Plywood Cladding

Exterior



Painted Treated Radiata Pine Plywood Cladding





CAUTION

**This product is to be kept dry
Cladding should be fixed the same day**

CEILING
2017

North





FRAMING
MOISTURE
CONTENT

CLADDING
MOISTURE
CONTENT



RELATIVE HUMIDITY



DRIVING RAIN & CLADDING
WETTING SENSORS



WEATHER STATION



SILL
MOISTURE
CONTENT



INDOOR
TEMPERATURE &
RELATIVE
HUMIDITY







Field Testing While Monitoring (NZ 4284)





Water Testing and Leak Tracing - While Monitoring



During Testing

Laboratory Testing – “Perfectly” Built Test Hut



The hut that was built to leak

Rob Stock · 11:39, Jul 04 2018



SUPPLIED

A small building, called a test hut, has been built specifically by the Ministry of Education to see whether it would leak in a bid to gather evidence for its leaky schools claim.




Figure 17.11 Test hut North and South walls, exterior view, leaking from façade testing

Key Findings from Field Monitoring & Testing

→ Primary Failure Causal Factors in order of impact:

1. Water leakage through “compliant” interface details
2. Exposure to driving rain (overhangs, site, Location)
3. Base-of-panel absorption
4. Centre-of-wall wetting (in exposed areas only)


WUFI Model Development and Calibration



AIR TEMPERATURE, RELATIVE HUMIDITY, WIND SPEED AND DIRECTION MONITORING ON ROOF




RADIATION AND RAIN MONITORING ON EXTERIOR WALL ORIENTATION




INSIDE SCHOOL

Transfer coefficients (input) agree.



Transfer coefficients (output) agree.




related and

V
A/


Solar Absorptivity

ASTM E1918


Thickness [m]




Exterior Paint and Cladding Condition




Cladding Colour




Orientation of Walls



Driving Rain Volume and Frequency



Rain Exposure



Interior Vapour Levels/Control

Relatable Risks – Visible Mould

Table 3.4 VTT mould index sensitivity classes – Example Generic Materials (Ojanen, et al., 2010)

Sensitivity Class	Example Materials
Very Sensitive	Untreated wood
Sensitive	Planed wood, paper-coated products, wood-based boards
Medium Resistant	Cement- or plastic-based materials, mineral fibres
Resistant	Glass and metal products, materials with protective treatments

Mould Index	Description
0	No mould growth
1	Initial stages of growth (microscopic)
2	<10% microscopic. Several local mould growth colonies (microscopic)
3	<10% visible mould growth on surface; New spores produced
4	10 – 50% coverage of visible mould growth on surface, >50% microscopic
5	>50% visible mould growth on surface
6	Heavy and tight mould growth, up to 100% coverage



2019/01/14



2019/01/20



2019/01/28



2019/02/05



2019/02/15





2019/02/28



Cladding Samples

Mould Growth within 97% RH Chamber



Stud and Building Paper Samples



Relatable Risk - Center of Wall in Plywood Cladding




Relatable Risks – Wood Decay




Decay Rating	Description	Dose Units
0	Sound – no decay	0-150
1	Slight Decay	150-500
2	Moderate Decay	250-600
3	Severe decay	350-800
4	Very severe decay	500+

Relatable Risk at Rainwater Leak





Leakage Location Mould Index



Sensitive/Very Sensitive Mould Resistance


Monitoring Results – Center of Wall (no Leaks)

Centre of Wall Shadowclad Mould Index (Sensitive)




Sensitive


Relatable Risks - Mold vs NZ Risk



Relatable Risks - Visible Mold VS NZ Risk Score - Cladding Only



Risk Score & Mould Index - Leak Locations (compliant)



Key Findings from Field Monitoring & Testing

- Primary Failure Causal Factors in order of impact (Visible Mold):
1. Water leakage through “compliant” interface details
 2. Exposure to driving rain (overhangs, site, Location)
 3. Base-of-panel absorption
 4. Centre-of-wall wetting (in exposed areas only)

Phase 2 –Red Herrings and Rebuttals

Taking publications and papers out of context and opining to discredit our methodology.

Defendant Expert Red Herring:

“WUFI is popular despite its inability to provide reasonable predictive outcomes unless used by an experienced and sophisticated user who already ‘knows’ the correct outcome.”
Lstiburek, Ueno, & Musunuru, 2015

RDH Rebuttal:

Your expert left out the following sentence:

“ In fact, despite the sophistication of the numerical analysis, available research is still dominated by experiment. We must still “build it, wet it, and watch it”. The observed outcomes are then used to “tune” available models. The field remains phenomenologically based, because there is no widely accepted theory of combined heat and moisture flow “.

The process we have taken in our work for this case is exactly what Lstiburek recommends in this quote. We are sophisticated users who installed monitoring into existing buildings, and we tested them by wetting, monitoring and watching them. With this knowledge we tuned our hygrothermal models so that they were accurate and useful.

Phase 2 –Red Herrings and Rebuttals

Taking publications and papers out of context and opining to discredit our methodology.

Defendant Expert Red Herrings:

1. *“The outputs from the WUFI software cannot precisely account for all factors in the real world.”*¹ (John Straube, Eric Burnett, “Overview of Hygrothermal (HAM) Analysis Methods” pg. 8)
2. *The plaintiffs’ experts “tampered with their WUFI models by using their monitoring data to manipulate them.”*

RDH Rebuttal:

“The gold standard for research-grade studies is to conduct a physical experiment and benchmark the model output results to the physical measurements... Physical testing, supported by modeling, an understanding of building science and building practise is not only an acceptable means of understanding and predicting the behaviour and long-term performance of building enclosures, this combination is the best approach available to science and industry. In this case, RDH’s WUFI modelling is backed by the things I have set out above”

Red Herrings and Rebuttals

“Cherry picking” test openings and observations at schools to support their opinions.

Defendants
Expert Report
confirming
excellent field
performance
when installed
correctly



RDH Rebuttal
Report showing
locations of test
openings and
simulation
results
predicting this
performance



Red Herrings and Rebuttals

Performing testing using a nonstandard methodology and making erroneous conclusions.

Defendants' expert team constructed and tested 3 samples to NZ 4284 at 300Pa:

Sample 1 - How it should have been built then (compliant + best industry practice)

Sample 2 - How it would be built today (compliant with current installation manual)

Sample 3 - How the schools were built - complete with installation "defects"

Result:

All Samples Passed

Defendants Conclusion:

Cladding is not the problem


QED or WTF?

Red Herrings and Rebuttals


Testing using a nonstandard methodology and making erroneous conclusions.



Roofing underlayment used NOT building paper or red "do not get wet" building paper





How to Calibrate Component Airtightness (Site to Lab)



15mm hole

Sum #1





Defendants Report -Thermographic scan after water testing Sample 2



NOTE: Moisture in plywood panels 1 through 10, 14 through 17 and 27 are as a result of the water spray and test pressures applied during AS/NZS 4284 Testing.

These anomalies are where they did not remove B.P.





IR Photography provided by of Mr. Richard Gibbs with Facadelab Ltd.

Base of water looks much better than Sample 3 due to heavy edge treatment + heavy



Panel Color Key







Rebuttal - Thermography Analysis



Rebuttal - Thermography Analysis





Defendants Expert Testing (Pass?)
 RDH Test Hut Monitoring Results
 RDH 2D WUFI Simulation (3 months)
 RDH Field Investigation




Figure 3.29 Test Hut Sheet "W" Unpainted face/edge (left), unpainted edge (centre) and painted edge (right) predicted RH distribution after the first 3-months of modelling from April to July.

Bonus: No Non-Disclosure Agreement


LAW

2 

Carter Holt Harvey settles billion dollar leaky schools case


The terms of the settlement with the Ministry of Education are unknown.






Wood Facades - “Time of wetness” Matters

There are no industry standard façade tests for time of wetness.




Wood Facades - “Time of wetness” Matters

There are no industry standard façade tests for time of wetness.



Wood Facades - “Time of wetness” Matters

There are no industry standard façade tests for time of wetness.



Accoya



Accoya = Acetylated Radiata Pine

RDH Wood Cladding Weathering Study Observations

INTERNAL USE

FEBRUARY 5TH , 2024 UPDATE

Graham Finch, Dipl.T., M.A.Sc., P.Eng.
Principal, Senior Building Science Specialist

Marc Imrich, B.A.Sc., EIT
Building Science Engineer (EIT)



Accoya New



Accoya after
16 months



Hemlock after
16 months

Time of Wetting – Good vs Bad

Good – Warm, dry and protected by the building enclosure 😊



Bad – exposed to weathering ☹️



Discussion + Questions

bch@rdh.com

Learn more at
rdh.com

 RDH Building Science

 @RDHBuildings