Mold Control in **Publicly Funded** Housing Developments

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





Major health related building problems in public housing can be traced back to MOISTURF.



Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





Water leakage, condensation, and high relative humidity create environments that are ideal for mold growth.




Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





This moisture damage is pervasive throughout the United States.



Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III



4

This moisture damage can be readily divided into three categories:



- Rain and Ground Water Leakage
- Leaking Pipes
- Condensation

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





The solution is to require that housing that is built with public dollars provide the following:

- Control of Rain Water or Ground Water Leakage
- No Leaking Pipes
- Control of Condensation
- Control of Interior Generated Moisture

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





In existing housing that is redeveloped or renovated this means:

- Fix or replace leaky roofs and windows
- Fix damp basements, crawlspaces or slabs
- Fix or replace water or steam heating and plumbing systems
- Provide mechanical ventilation/air change
- Replace old windows with EnergyStar windows
- Improve building envelope (air tightness and thermal performance)

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





In new housing this means:

- Provide proper design of roof, wall and foundation assemblies to ensure low maintenance moisture control and air leakage control (BUILDING AMERICA STANDARDS).
- Design plumbing and HVAC systems that can be accessed and maintained. (A maintenance budget for these systems is a must)
- Provide quiet, power efficient continuously operating fans.
- Provide EnergyStar windows

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





Case Studies Mold Complaints in Public Housing 1989-1999

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III







EXISTING CONDITIONS

- Built in 1973
- Single story, full basement
- 1100 square feet
- 3, 4, or 5 bedrooms and 1 or 2 bathrooms
- High occupant loading

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III







NATURE OF COMPLAINT

 Staining of exterior wall corners in living spaces, presence of condensed moisture on windows and mold

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III







NATURE OF COMPLAINT

> Staining of concrete basement walls with moisture and mold

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Additional Considerations
 - In 1980, an additional 6 inches of insulation was added
 - soffit vents were blocked off
 - louvers were installed in each gable to provide passive attic venting
 - original aluminum double-hung single-pane windows were replaced with vinyl double-pane units
 - homes heated by forced-air, atmospherically vented (coupled), oil-fired furnaces, in the basements

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III







Test Results

- 5 to 9 airchanges per hour at a depressurization pressure of 50 Pascals
- typical leakage or tightness for houses of this type, age, and location

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Conclusions: The problems are a result of:
 - High levels of interior generated moisture
 - Cold building enclosure interior surface temperatures
 - Lack of air change

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Recommendations
 - 1. Reduce the interior vapor pressure/moisture
 - This can be accomplished by:
 - Reducing the rate of moisture generation by venting cooking appliances and clothes dryers.
 - Increasing the rate of moisture removal by installing a controlled ventilation system, based on occupancy, limiting rh to 30 percent at 70° during the winter months.
 - Both of the above strategies are recommended.

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Recommendations (con't)
 - 2. Increase the temperature of the cold surfaces.
 - This can be accomplished by:
 - Adding thermal insulation to the interior surfaces of the perimeter concrete basement walls. Rigid insulation should be installed from the basement floor slab level to the underside of the main floor plywood sub floor.
 - Taping vertical joints in the rigid insulation.
 - Blocking basement window openings with rigid sheet insulation and masonry).
 - All of the above strategies are recommended.

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Recommendations (con't)
 - 3. Increase air circulation (increasing heat flowing to a surface)
 - This can be accomplished by:
 - Cutting vent louvers in all bedroom closet doors, or all the bedroom closet doors should be replaced with louvered doors to promote air circulation and therefore heat flow into closet spaces.
 - 4. Check perimeter attic insulation. Install wind baffles to prevent "wind -washing".
 - 5. Insulate basement cold water / hot water pipes.

NOTE:Replacing the original aluminum windows was a positive step in increasing the temperature of cold, potentially condensing surfaces.

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





Existing Conditions



- 1990 duplex units -two story wood frame structures constructed over cast concrete basement foundations and basement floor slabs.
- Space conditioning systems are gas fired, high efficiency aerodynamically uncoupled.
- Exhaust fan systems in the kitchen and bathroom were installed, however they did not extract noticeable quantities of air

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III







Nature of Complaint

- Sensations of dampness
- Mold and window condensation,
- Window deterioration
- Interior paint and gypsum wall board damage

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Test Results
 - 2 to3 air changes per hour at a depressurization pressure of 50 Pascals
 - units are of unusually "tight" construction, a sign of good detailing and good workmanship

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Conclusions: The problems are a result of:
 - High levels of interior generated moisture due to high occupant loading
 - Lack of air change due to absence of controlled ventilation

Note: Great windows and a well insulated and detailed building envelope still requires air change

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Recommendations
 - Reduce the interior vapor pressure/moisture by installing a controlled mechanical ventilation system
 - Exhaust fans of 100 to 150 cfm capacity should be installed, extracting air from the washrooms, and basement area.
 - The fans should be operated continuously

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Cost
 - Installation is approximately \$250/unit (this is a retrofit).
 - The operating cost is approximately \$100/year for both energy and fan electricity.

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III







- ExistingConditions
 - Units range from 800 to 1,200 sq. ft.
 - 2 story, vented crawlspace
 - 8 units per building

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III







- Nature of Complaint
 - Rotting floor joists
 - Complaints of condensation on windows
 - Mold on interior walls at corners

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





Test Results

- Measured Moisture content in floor joists 18 to 28% by weight
- 2 to 3 air changes per hour at a depressurization pressure of 50 Pascals
- Typical tightness for units of this type, age and location

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Conclusions: Problems are a result of:
 - High moisture entry rate due to wet crawlspaces
 - Lack of air change due to absence of controlled ventilation

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Recommendations
 - Repace rotted framing members
 - Install continuous ground cover in crawl space
 - Install individual exhaust fans in each unit

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Follow-up
 - Rotted framing members were replace
 - Ground cover was installed
 - Fans were installed
 - No more complaints of rotting floors and mold

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III







- Existing Conditions
 - 1940's three story walk-up units
 - Units range from 500 to 800 sq. ft.
 - Renovations included new windows and high-efficiency heating

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III







- Nature of Complaint
 - Complaints of condensation on windows and mold growth



Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Test Results
 - Measured rh in excess of 65% @ 70• F during winter months
 - 1 to 2 air changes per hour at a depressurization pressure of 50 Pascals



Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Conclusions: The problems are a result of:
 - High levels of interior generated moisture due to high occupant loading, dirt crawlspaces, condensation on cold water pipes, cold exterior wall surfaces, and city storm drain backups.
 - Lack of air change

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Recommendations
 - Install central, continuous operation exhaust fans in each building.

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Follow-up
 - Owner installed bathroom and crawlspace fans
 - City repaired storm drains
 - Mold and condensation complaints eliminated
 - \$34 per apartment per year additional energy cost (\$85 per apartment per year if low efficiency heating)

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III







- ExistingConditions
 - Individual units ranged from 950 to 1,300 ft2 in floor area over two levels.
 - Steel framed, four story, multi-unit project
 - The space conditioning systems consisted of perimeter hydronic radiators coupled to a gas boiler system

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III







Nature of Complaint

- Complaints of mold
 - Lower units at the interior surfaces of exterior walls near basement floor slab locations;
 - Lower units at the interior surfaces of interior walls near basements floor slab locations;
 - Stairwells at interior surfaces near basement floor slab locations

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Test Results
 - 5 to 6 airchanges per hour at a depressurization pressure of 50 Pascals
 - Extremely leaky for multifamily apartment construction of this type, age and location



Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Conclusions: The problems are a result of:
 - Summer condensation due to cold surfaces in lower level garden style apartments
 - Warm, humid exterior air "sees" a cooled surface (especially at metal studs)
 - Moisture is deposited at the cooled surface leading to a rise in surface relative humidity and mold
 - Basement level units experience substantial heat loss to the ground at the below grade portions of the perimeter walls and bottom plates of interior walls
 - Warm, humid air enters and is cooled by the concrete foundation assembly
 - The mold growth is occurring as a result of thermal bridging leading to a rise in local surface relative humidity

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





Recommendations

- Install thermal breaks under bottom plates of interior and exterior walls
- Reconstruct the lower units to eliminate the thermal bridging at the exterior walls
- Strip the damaged gypsum board and place rigid insulation between the metal framing and concrete foundations at perimeter
- Install individual exhaust fans in each unit

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Follow-up
 - Fans were installed, thermal bridging was eliminated, and walls were insulated and sealed
 - No more complaints of mold

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Existing Conditions
 - 1980 7 story apartments
 - Concrete frame structure with block infill walls with stud back-up with gypsum on both sides
 - Space conditioning systems are gas fired centrally located boilers with individual vertical fan coil units



Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III








- Nature of Complaint
 - Water infiltration
 - Mold and window condensation
 - Window deterioration
 - Interior paint and gypsum wall board damage

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Test Results
 - Water leakage through facade



Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Conclusions
 - Rain water entry is occurring at the slab edge locations under the fabric flashings
 - Discoloration at the ceiling/exterior wall intersections is due to mold growth as a result of thermal bridging

 $\label{lem:building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III$





2 x 4 wood frame wall (16" o.c.) screwed through rigid insulation into 2 x 4 furring strips with 7" long 2 x 4 pressure wood screws treated furring strips screwed into block 1/2" plywood shims @ 24" exterior wall with vertical centers expansion anchors inserted in pilot 1 1/2" rigid insulation nailed into 2 x 4 furring through building paper 30# building paper installed shingle fashion (stapled into 2 x 4 furring) 1/2" diameter weep holes Faced 3 1/2" fiberglass batt drilled every insulation vertical block ioint

Recommendations

- Create a "water dam" and drainage path at locations where water is entering the building
- Eliminate the existing thermal bridge affect of the concrete frame

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





Existing Conditions



- 2 years old single family residences
- One story wood frame structures constructed predominantly over basement foundations. Portions of some units are constructed over elevated pier foundations.
- Wall assemblies are 2x6 with plywood sheathing, housewrap and cedar shingles.
- Roof assemblies are curved, rigid foam insulated stress skin panels with a roofing membrane.

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Nature of Complaint
 - sensations of dampness
 - mold
 - window condensation and window deterioration
 - interior paint and gypsum wall board damage



Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III







- Existing Conditions (con't)
 - Windows are double glazed, low E wood frame windows
 - Space conditioning systems are propane fired boilers with hot water radiation.
 - Exhaust fan systems in the kitchen and bathrooms are installed.
 - 2, 3 and 4 bedroom -floor areas -1,200 and 1,500 square feet

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





Test Results

- 1 to 1.5 air changes per hour at a depressurization pressure of 50 Pascals
- The units are of unusually "tight" construction, among the tightest units of this size, age and type of occupancy we have tested

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Conclusions: The problems are a result of:
 - Lack of air change

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





Recommendations

- Reduce the interior vapor pressure/moisture by installing a controlled mechanical ventilation system:
 - Exhaust only ventilation strategy
 - A single exhaust fan of 100 to 150 cfm capacity should be installed in each unit, ducted from each bedroom resulting in air extraction from each bedroom

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III







Existing Conditions

- Two story uninsulated masonry structures constructed just after the Second World War.
- Space conditioning systems are hydronic radiators connected to a central heating system not located within units.
- No controlled mechanical ventilation such as exhaust fan systems in the kitchens or bathrooms were installed.
- The units had recently (within the past few years) undergone window replacement.

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III







- Nature of complaint
 - Sensations of dampness
 - Mold
 - Window condensation and window deterioration
 - Interior paint and plaster board damage

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Observations and Test Results
 - High occupant loading in relatively small units
 - Occupant lifestyles also inferred high moisture generation (hanging interior laundry, cooking, cleaning, etc.)
 - Mold was observed at exterior corners
 - Condensed water and water stains on window frames indicated significant current and past condensation on the window glass

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Conclusions
 - Sensations of dampness occur as a result of high interior moisture levels due to
 - inadequate air change (ventilation) and
 - a high moisture source strength (high occupant loading and lifestyle);
 - The mold and mildew, window condensation, interior paint and plaster board damage occur as a result of
 - high interior moisture levels due to inadequate air change (ventilation) and
 - a high moisture source strength (high occupant loading and lifestyle)
 combined with cool surfaces

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





Recommendations

- Reduce the interior vapor pressure/moisture by installing controlled mechanical ventilation :
 - Operate ventilation continuously
 - Maintain interior moisture levels between 30 and 45 percent relative humidity at 70 degrees Fahrenheit
 - Exhaust only ventilation fans of 150 cfm capacity should be installed, extracting air from the washrooms and stairwell/hallway areas and exhaust this air to the exterior via a duct
 - To promote air change in the secondary rooms, all interior doors should be undercut 2.5 inches (from top of floor covering to underside of door) or install transfer grills

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III







Existing Conditions

- State funded development
- Completed in 1939
- Renovated in 1987-1990 at cost of \$100,000/unit
- 540 apartments
- 1,510 Residents
- 16 City Blocks

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





Conclusions

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III



Conclusions

- In order to insure that publicly funded housing provides healthy environments for its occupants minimum performance standards must be set
- These performance standards must be measurable and achievable

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





Conclusions

 Long-term solutions will require a collaborative response from housing, public health, and urban planning institutions beginning with systematic surveys of existing conditions

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





Recommendations

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III



Recommendations

- Standards must be set and tested for compliance in the following categories:
 - Rain water and ground water control
 - Thermal bridge control
 - Foundation wall, crawl space, and slab insulation
 - EnergyStar windows
 - Forced water and steam distribution systems
 - Fresh air supply and distribution

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





Recommendations

- Develop effective professional and community partnerships
- Set realistic short term and long term priorities
- Leverage multiple funding sources
 - Housing, Health, and Energy
- Consolidate multiple service delivery systems

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III







- Nature of Complaint
 - Community concern about poor resident health*

*BU/ Tufts Study October, 1998

Public Health in Public Housing: A
Survey of W. Broadway Housing
for US EPA Region 1


Professors Pat Hynes and Doug Bruggie

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





Observations and Test Results - Summary



Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





 Observations and Test Results - Moisture Sources

Ceiling water leaks	38%
Wall water leaks	17%
Toilet, tub, sink leaks	24%
 Radiator leaks 	22%

Floor and/or ceiling condensation 17%

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





 Observations and Test Results - Other Moisture Variables

Mold growth	20%
-------------------------------	-----

- Air is stuffy58%
- Leave windows open in winter 82%
- Use oven to heat apartment24%

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





 Observations and Test Results - Health Problems

 Reports asthma diagnosis 	26%
 Reports other respiratory 	30%
 Reports allergies 	40%
 Symptoms in last month 	
Headache	56%
Coughing	46%
 Symptom stops outside apartment 	40%

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





Observations and Test Results - How are Building Problems Currently Addressed?

Residents understand how to submit 100%

a work order

Maintenance staff is responsive 72%

Residents make repeated requests 50%

for the same problem

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





- Observations and Test Results Health Costs
 - 20% of pediatric ER is asthma related
 - -\$500 \$800 per ER visit
 - -\$1,000 \$2,000 per overnight stay
 - -3-1/2 days for average asthma stay
 - Poor environment conditions accelerate cases of severe asthma

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





Recommendations

- Improve building repair practices
- BHA needs a housing, public health, and urban planning collaborative to solve these problems
- BHA should perform systematic surveys of housing and health conditions

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





Conclusion

- Physical building problems are a significant public health problem at W. Broadway
- A "clinical" response advising tenants how to improve their health is insufficient to solve the health problems
- Standard building rehabilitation practices did not guarantee good health conditions at W. Broadway
- Long-term solutions will require a collaborative response from housing, public health, and urban planning institutions and residents

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III





Follow up

- South Boston Neighborhood Health Center Indoor Air Quality Initiative
- Boston Medical Center/ NIH Asthma Study
- EPA Rare Grant Asthma mitigation
- BHA Energy Performance Contract
- BHA Energy Master Plan
- BHA Health, Energy, and Housing Initiative

Building Science Corporation/Peregrine Group/Bugs, Mold, and Rot III



