## Dotals for Hold-Froe Homes

#### PACNY Annual Environmental Conference April 15, 2005





# Ideal Enclosure Construction

- Build with dry materials
- Allow no water to get into the assemblies during construction
- Dry any assemblies or elements that get wet prior to closing up





### Enclosure Design Theory

- Prevent assemblies from getting wet from the outside
- Prevent assemblies from getting wet from the inside
- Should assemblies get wet or start out wet, allow them to dry to the interior, exterior, or both



Building AMERICA AMERICA

### Hygric Balance

## How BuildingsGet Wet


- From the outside
- From the inside
- Start out wet

# How BuildingsDry


- Dry to the Outside
- Dry to the Inside



April 14. 2005



1x4 furring (16" o.c.)



Concrete slab




### Definition of a Moisture Problem

- It's a rate issue, that is, when the rate of wetting is greater than the rate of drying accumulation occurs.
- Problems don't occur until the quantity of accumulated moisture exceeds the moisture storage capacity of the material, system or assembly.
- The moisture storage capacity is specific
  - time
  - temperature
  - material





# Shed the water from the face of the building








April 14. 2005

# Keep the groundwater from entering the building at the foundation




April 14. 2005




#### What can go wrong?



#### Drainage Planes are Required Where it Rains



#### **Bad - no drainage plane**



#### **Good - drainage plane provided**





# What can go wrong with a well built house?




- 1/2 GWB over poly
- R-13 unfaced batts
- 1/2" Insulating Sheathing as drainage plane
  - Brick veneer






#### **Keep cavities clear for drainage**







#### **Keep cavities clear for drainage**







#### Plastic Vapor Barriers Often Keep Assemblies Wet Rather than Prevent Them From Getting Wet

#### **Exterior Conditions**


Temperature: 80°F Relative humidity: 75% Vapor pressure: 2.49 kPa

#### Conditions within Cavity:

Temperature: 100°F Relative humidity: 100% Vapor pressure: 6.45 kPa

#### Interior Conditions

Temperature: 75°F Relative humidity: 60% Vapor pressure: 1.82 kPa



#### nce.com

Vapor is driven both inward and outward by a high vapor pressure differential between the brick and the interior and the brick and the exterior.

nce.com

### © buildingscience.com
















**April 14, 2005** 



# What can go wrong with a well built house?



- 1/2 GWB over poly
- R-13 unfaced batts
- · Housewrap
  - Cedar Clapboards





### What went wrong?





#### Back vent siding to uncouple it from the wall







### What went wrong?



### Wrap window openings





#### **Provide Flashing Around Intentional Openings**








#### Dilute Interior Moisture Load with a Ventilation System


•Exhaust ventilation single- or multi-point


© building

- Supply ventilation single- or multi-point integrated with central system fan
- •Balanced ventilation single- or multi-point integrated with central system fan with or without heat or energy recovery

© building









April 14. 2005



### Six Steps to Mold-Free Homes

- 1. Keep the groundwater from entering the building at the foundation
- 2. Keep the rain off the face of the building
- 3. Uncouple the cladding from the sheathing
- 4. Provide good flashing systems to keep the water out of the wall
  - This includes windows and doors and other penetrations such as vents, electrical connections, and plumbing.
- 5. Allow the wall to dry to the interior by not installing polyethylene or other impermeable materials
  - Vapor barriers should never be installed on the inside of air conditioned buildings
- 6. Dilute the interior moisture load by providing controlled mechanical ventilation

PR-0509a: Details for Mold-Free Homes



